

CI/SfB 125	(2-)		(W7)
Common Arrangement C40/J30/J31/P22			

**Project: Onsite Renovation and Protection**  
**Title: Rancho don Catarino, Santiago Tlanguistenco, Mexico**  
**Date: February 2004**

The homeowners of this beautiful five bedroom countryside retreat requested that all of the glass was renovated and protected with the ClearShield System. The problems that affected the glass were moisture, tree sap and birdlime, all of which contaminated the glass and proved difficult to remove.

Over 160m<sup>2</sup> of interior and exterior glass was treated onsite by Transparencia en Servicios, a licensed applicator of the ClearShield System based in Mexico City.

Following the simple After-Care programme ensured the glass was kept looking pristine for longer, without the use of harsh cleaning products or methods.



*All interior and exterior glass was renovated and protected with the ClearShield System*